

Mission Public School District

2016/2017 Water Testing Program - Lead Content

Test Date	Water Fixture	Location	Lead Level	Mitigation Action
1. Albert McMahon Elementary (built 1989)				
3/1/17	Ceramic Drinking Fountain	Outside gym	0.028	decommissioned
3/1/17	Drinking Fountain and sink	Room 116	0.054	fountain decommissioned, sink signage - flush for 2 minutes before use
3/1/17	Kitchen Sink	1st Aid Room	0.019	Signage - flush for 2 minutes before use
3/1/17	Kitchen Sink	Pac Kitchen 99A	0.016	Signage - flush for 2 minutes before use
3/1/17	Kitchen Sink	Room 118	0.035	Signage - flush for 2 minutes before use
3/1/17	Kitchen Sink	Room 119	0.009	
3/1/17	Drinking Fountain	Between Room 120 & 122	0.009	
3/1/17	Kitchen Sink	Room 126	0.009	
3/1/17	Drinking Fountain	Between Room 107 & 109	0.021	decommissioned
3/1/17	Drinking Fountain	Between Room 108 & 110	0.013	decommissioned
3/1/17	Drinking Fountain	Room 102	0.007	
3/1/17	Drinking Fountain	Room 101	0.001	
2. Cherry Hill Elementary (built 1976)				
2/6/17	Drinking Fountain	Room 57	0.002	
2/6/17	Drinking Fountain	Room 55	0.001	
2/6/17	Kitchen Sink	Room 54	0.002	
2/6/17	Drinking Fountain	Outside PAC Kitchen	0.001	
2/6/17	Drinking Fountain	Room 35 Mezzanine	0.011	decommissioned
2/6/17	Drinking Fountain	Room 6	0.009	
2/6/17	Drinking Fountain	Room 7	0.016	decommissioned
2/6/17	Drinking Fountain	Room 21	0.475	decommissioned
2/6/17	Drinking Fountain	Room 10	0.001	
2/6/17	Drinking Fountain	Room 13	0.000	

Mission Public School District

2016/2017 Water Testing Program - Lead Content

Test Date	Water Fixture	Location	Lead Level	Mitigation Action
3. Dewdney Elementary (built 1924)				
12/12/16	Drinking Fountain	Room 201	0.012	decommissioned
12/12/16	Drinking Fountain	Hall Between Rooms 107 & 108	0.031	decommissioned
12/12/16	Drinking Fountain	Room 110	0.026	decommissioned
12/12/16	Kitchen Sink	Staff room 127	0.012	Signage - flush for 2 minutes before use
12/12/16	Drinking Fountain	Hall Across from Room 126	0.011	decommissioned
12/12/16	Kitchen Sink	Room 128	0.004	
3/20/17	Drinking Fountain	Room 200	0.041	decommissioned
3/20/17	Drinking Fountain	Room 201	0.001	
3/20/17	Drinking Fountain	Room 109	0.009	
3/20/17	Drinking Fountain	Room 133	0.042	decommissioned
3/20/17	Drinking Fountain	Room 111	0.040	decommissioned
3/20/17	Kitchen Sink	Health Room 115	0.032	Signage - flush for 2 minutes before use
3/20/17	Drinking Fountain	Across from room 126	0.011	replace fountain with a new fountain/bottle filling station
3/20/17	Kitchen Sink	Room 125	0.001	

Mission Public School District

2016/2017 Water Testing Program - Lead Content

Test Date	Water Fixture	Location	Lead Level	Mitigation Action
4. École Mission Central Elementary (built 1990)				
3/13/17	Drinking Fountain	Between Room 124 & 125	0.010	decommissioned
3/13/17	Drinking Fountain	Between Room 116 & 117	0.003	
3/13/17	Kitchen Sink	PAC Kitchen Room 118	0.001	
3/13/17	Kitchen Sink	Room 127	0.002	
3/13/17	Kitchen Sink	Room 130	0.003	
3/13/17	Drinking Fountain	Outside Room 143	0.008	
3/13/17	Drinking Fountain	Room 139	0.004	
3/13/17	Drinking Fountain	Room 140	0.001	
3/13/17	Kitchen Sink	Staff Room 107	0.002	
3/13/17	Drinking Fountain	Between Room 107 & 156	0.010	
3/13/17	Drinking Fountain	Room 144	0.006	
3/13/17	Drinking Fountain	Room 148	0.001	
3/13/17	Drinking Fountain	Room 151	0.002	
3/13/17	Kitchen Sink	Between Room 151 & 145	0.004	

Mission Public School District

2016/2017 Water Testing Program - Lead Content

Test Date	Water Fixture	Location	Lead Level	Mitigation Action
5. École Mission Secondary Built 1950)				
12/28/16	Store Sink	Room 152	0.003	
12/28/16	Kitchen Glass Filler	Room 185	0.002	
12/28/16	Bakery Sink	Room 187	0.002	
12/28/16	Drinking Fountain	Between 154 & 156	0.003	
12/28/16	Bottle Filler	Between 165 & 167	0.000	
12/28/16	Kitchen Sink	Room 171	0.007	
12/28/16	Drinking Fountain	Between 175 & 173	0.001	
12/28/16	Drinking Fountain	Room 237	0.005	
12/28/16	Drinking Fountain	Room 239	0.002	
12/28/16	Drinking Fountain	by Washrooms	0.002	
12/28/16	Drinking Fountain/Bottle Filler	By Gym	0.001	
12/28/16	Drinking Fountain	Boys Changeroom	0.002	
12/28/16	Drinking Fountain	Fitness room 139	0.053	decommissioned
12/28/16	Kitchen Sink	Staff room 133	0.004	
12/28/16	Sink	Weight Room 121	0.172	
12/28/16	Drinking Fountain	By Girls Changeroom 119A	0.016	decommissioned
12/28/16	Kitchen Sink	Room 166	0.029	Signage - flush for 2 minutes before use
12/28/16	Drinking Fountain	Room 103	0.005	
12/28/16	STN 6 Kitchen Sink	Room 202	0.002	
12/28/16	STN 2 Kitchen Sink	Room 204	0.002	
12/28/16	Drinking Fountain	By Room 201	0.020	decommissioned
12/28/16	Drinking Fountain	by Room 209 & 213	0.001	
1/17/17	Planned Drinking Fountain	By Gym	0.012	re-piped, & replaced fountain with a new fountain/bottle filling station

Mission Public School District

2016/2017 Water Testing Program - Lead Content

Test Date	Water Fixture	Location	Lead Level	Mitigation Action
6. E.S. Richards Elementary (built 1951)				
12/19/16	Kitchen Sink	Staff room 127	0.003	
12/19/16	Drinking Fountain	Girls Change Room. Room 132C	0.024	decommissioned
12/19/16	Kitchen Sink	PAC Kitchen Room 130	0.003	
12/19/16	Drinking Fountain	Room 121	0.005	
12/19/16	Drinking Fountain	Room 123	0.058	decommissioned
12/19/16	Drinking Fountain	Across From Room 125	0.074	decommissioned
12/19/16	Drinking Fountain	Room 114	0.005	
12/19/16	Drinking Fountain	Across From Room 110	0.009	
12/19/16	Sink	Room 109	0.001	
7. Facilities (Ferndale) (built 1972)				
11/28/16	Sink	Room 124A	0.005	
11/28/16	Drinking Fountain	Rm 118 Hallway	0.019	decommissioned
11/28/16	Kitchen Sink	Room 114	0.001	
11/28/16	Staffroom Sink	Room 103	0.000	
8. Fraserview (built 1978)				
2/27/17	Kitchen Sink	Room 137	0.003	
2/27/17	Kitchen Sink	Staff Room 134	0.020	Signage - flush for 2 minutes before use
2/27/17	Drinking Fountain	By Main Entrance & Gym	0.001	
2/27/17	Faucet	Room 101	0.011	Signage - flush for 2 minutes before use
2/27/17	Drinking Fountain	Between Room 103 & 104	0.075	decommissioned
2/27/17	Kitchen Sink	Room 115	0.092	Signage - flush for 2 minutes before use
2/27/17	Kitchen Sink	Room 161	0.001	
2/27/17	Kitchen Sink	Room 163	0.022	Signage - flush for 2 minutes before use
2/27/17	Drinking Fountain	Between Room 109 & 108	0.014	decommissioned
2/27/17	Drinking Fountain	Between Room 154 & 155	0.008	

Mission Public School District

2016/2017 Water Testing Program - Lead Content

Test Date	Water Fixture	Location	Lead Level	Mitigation Action
9. Hatzic Elementar (built 1911)				
12/5/16	Drinking Fountain	Room 113	0.046	decommissioned
12/5/16	Drinking Fountain	Room 114	0.005	
12/5/16	Staff Kitchen Sink	Room 108	0.014	Signage - flush for 2 minutes before use
12/5/16	Drinking Fountain	Across from Office Rm 100	0.010	
12/5/16	Kitchen Sink	Room 129	0.004	
12/5/16	Drinking Fountain	Room 119	0.013	decommissioned
12/5/16	Drinking Fountain	Room 122	0.018	decommissioned
1/17/17	Drinking Fountain	Across from Office Rm 100	0.005	
10. Hatzic Middle School (built 1972)				
2/20/17	Glass Filler	Caf. Counter	0.054	decommissioned
2/20/17	Kitchen Sink	Caf. Middle Counter	0.004	
2/20/17	Kitchen Sink	Store	0.008	
2/20/17	Drinking Fountain	Outside Drama Room	0.008	
2/20/17	Drinking Fountain	Big Gym Girls Side	0.003	
2/20/17	Drinking Fountain	Metal and Wood Shop	0.013	decommissioned
2/20/17	(w) Drinking Fountain	Across from Room 340 Library	0.007	
2/20/17	Kitchen Sink	Room 346 Foods NW	0.002	
2/20/17	Drinking Fountain	By room 346A	0.006	
2/20/17	Faucet	Room 302A	0.004	
2/20/17	Kitchen Sink	Staff room 307	0.007	
2/20/17	Drinking Fountain	Outside Room 307d	0.007	
2/20/17	Drinking Fountain	1st Floor Between Staff Rooms	0.002	
2/20/17	Drinking Fountain	2nd Floor Between Staff Washrooms. Plugged Drain.	0.014	decommissioned

Mission Public School District

2016/2017 Water Testing Program - Lead Content

Test Date	Water Fixture	Location	Lead Level	Mitigation Action
11. Hillside Elementary (built 1982)				
2/8/17	Drinking Fountain	Outside Room 109	0.035	decommissioned
2/8/17	Kitchen Sink	PAC Kitchen Room 123A	0.002	
2/8/17	Drinking Fountain	Outside Mech Room 109C	0.014	decommissioned
2/8/17	Kitchen Sink	Staff Room 105	0.001	
2/8/17	Drinking Fountain	Room 111	0.005	
2/8/17	Drinking Fountain	between room 106B & 106C	0.001	
2/8/17	Drinking Fountain	Room 113	0.006	
2/8/17	Drinking Fountain	Room 131	0.006	
2/8/17	Drinking Fountain	Room 133	0.004	
2/8/17	Drinking Fountain	Between Room 107 & 108	0.005	
2/8/17	Drinking Fountain	Room 117	0.002	
2/8/17	Faucet	Room 120	0.002	
12. School Board Office (built 1972)				
2/27/17	Kitchen Sink	Room 110	0.012	Signage - flush for 2 minutes before use
2/27/17	Kitchen Sink	Room 211A Copyroom	0.011	Signage - flush for 2 minutes before use
2/27/17	Drinking Fountain	Outside Room 305	0.003	
2/27/17	Kitchen Sink	Staff Room 308	0.001	
2/27/17	Kitchen Sink	Outside Room 225	0.001	

Mission Public School District

2016/2017 Water Testing Program - Lead Content

Test Date	Water Fixture	Location	Lead Level	Mitigation Action
13. Silverdale Elementary (built 1959)				
1/30/17	Drinking Fountain	Between Room 115 & 116	0.001	
1/30/17	Drinking Fountain	Room 111	0.026	decommissioned
1/30/17	Drinking Fountain	Room 110	0.007	
1/30/17	Kitchen Sink	Room 135	0.001	
1/30/17	Sink	Staff Room 134	0.002	
1/30/17	Drinking Fountain	Gym	0.004	
1/30/17	Drinking Fountain	Room 102	0.030	decommissioned
1/30/17	Drinking Fountain	Room 150	0.001	
1/30/17	Drinking Fountain	Room 100	0.011	decommissioned
14. West Heights Elementary (built 1958)				
1/9/17	Drinking Fountain	By Room 133 & 132	0.065	decommissioned
1/9/17	Kitchen Sink	PAC Room 156	0.001	
1/9/17	Drinking Fountain	By Room 110	0.026	decommissioned
1/9/17	Drinking Fountain	Room 136	0.001	
1/9/17	Drinking Fountain	Room 116	0.011	decommissioned
1/9/17	Drinking Fountain	Room 121	0.010	
1/9/17	Kitchen Sink	Room 217	0.005	
1/9/17	Faucet	Room 152	0.004	
1/9/17	Faucet	Room 136	0.011	Signage - flush for 2 minutes before use
1/9/17	Drinking Fountain	Room 140	0.049	decommissioned

Remaining Sites to be tested in 2017 /2018 School Year

Built

- 1992 Christine Morrison
- 1996 Deroche
- 1982 Durieu
- 1953 Grounds Shop
- 1996 Heritage Park

Built

- 1989 Riverside
- 1993 Stave Falls
- 1982 Transportation
- 1994 Windebank